


2014 CHEVROLET SILVERADO K1500 LTZ

Pickup | 8 Cylinders | Gas


1GCVKSEC7EZ146168 

Country of Assembly: United States
Last Reported Odometer: 22,024 KM

LIEN CHECK



No Lien Records Found



Accident/Damage Records Found



Last Registered In:
Manitoba (Normal)



12 Service Records Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.


Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of August 16, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check

Lien Check

 No lien records found in **Manitoba**.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each

CARFAX Canada Canadian Lien Guarantee

If for some reason our lien check fails to accurately reflect the

1GCVKSEC7EZ146168

been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.



that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2016 Jul 5	Manitoba, Canada	
	Estimate: Front Estimate Date: n/a	\$721.77
	Claim: Non-collision Front	Not Reported
2017 Jul 1	Manitoba, Canada	
	Estimate: Rear Estimate Date: n/a	\$1,701.45
	Claim: Vandalism Rear	Not Reported



Registration

This vehicle has been registered in the province of **Manitoba in Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Oct 3		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Nitrogen fill tires Bed liner installed
2014 Feb 3		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Body computer/module replaced Exhaust secured Engine/powertrain computer/module reprogrammed
2014 Feb 26		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed Key(s) (re) programmed
2014 Jul 4	10,073 KM	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Battery replaced Oil and filter changed Instrument cluster reprogrammed Transfer case operation checked
2014 Oct 30	22,024 KM	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Accessories installed Heated seat repaired Oil and filter changed
2015 Nov 25		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> License plate light bulb(s) replaced

DATE	SOURCE	DETAILS
2015 Dec 4	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Console armrest replaced
2015 Dec 14	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Convertible top replaced/repaired
2016 May 16	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced
2016 Jun 3	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Trailer hitch installed
2016 Aug 15	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Front differential fluid flushed/changed • Four wheel alignment performed • Brake fluid flushed/changed • Fuel injection system flushed/serviced • Rear differential serviced • Transfer case serviced • Wiper(s) replaced
2016 Aug 24	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tonneau cover installed

Open Recalls

Recall #: 2016007 | Frontal Airbag and Pretensioner Non Deploy Recall Date: 2016 Sep 09

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2014-2017 model year Chevrolet Silverado LD, GMC Sierra LD, Buick Encore, Chevrolet Trax, Chevrolet Caprice Police, and Chevrolet Corvette vehicles, 2014-2016 model year Buick Lacrosse, Chevrolet Spark EV, and Chevrolet SS vehicles and 2015-2017 model year Chevrolet Silverado HD, GMC Sierra HD, GMC Yukon, GMC Yukon XL, Cadillac Escalade Cadillac Escalade ESV, Chevrolet Suburban, and Chevrolet Tahoe vehicles. The sensing and diagnostic module (SDM) in these vehicles, which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain rare circumstances. If the frontal airbags and seatbelt pretensioners do not deploy when required, there is an increased risk of injury to occupants in a crash.

Remedy

Reprogram the SDM with new software that eliminates this defect. In vehicles with any previous deployment events recorded in the SDM, dealers will replace the existing SDM with a new SDM prior to programming and setup. Note: Before replacing the SDM, any airbag related Diagnostic Trouble Codes should be identified, diagnosed, and corrected prior to SDM replacement. Faulty SIR components in need of replacement are unrelated to this safety recall and are not covered under the terms of this safety recall.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit [GM's website](#).

Recall #: N172085440 | Loss of Steering Assist Recall Date: 2017 Jun 29

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2014 model year Chevrolet Silverado LD and GMC Sierra LD vehicles. These vehicles may experience a temporary loss of electric power steering (EPS) assist followed by a sudden return of EPS assist, particularly during low-speed turning maneuvers. The loss and sudden return of EPS assist typically happens within a 1 second period and is caused by an electrical/software issue. If EPS assist is lost and suddenly returned, the driver could lose temporary control of the steering wheel, increasing the risk of a crash.

Remedy

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit [GM's website](#).

Recall #: N192220470 | Power Sliding Rear Window Defroster Failures (Canada Only) Recall Date: 2019 Jun 27

Recall Description

General Motors has approved a safety recall in Canada for certain 2014-2019 model year Chevrolet Silverado and GMC Sierra vehicles equipped with a power sliding rear window (RPO A48). In some of these vehicles, areas of high electric resistance on the rear defroster circuit, caused, in part, by mechanical stress from opening and closing the rear power window, intrusion of debris, and use of the rear defroster may, over time, generate heat which could melt the areas surrounding the circuit. In rare instances, this heat could cause a non-propagating fire, increasing the risk of property damage or injury.

Remedy

Dealers will replace the buss bar covers and the contact cover, and for certain vehicles, will reprogram the HVAC calibration to disable the rear defroster from automatically turning on at keyed start. Please note that the rear defroster will automatically turn on during remote start or by pushing the manual button and is not affected by this calibration. If the rear window or sliding glass assembly appears damaged due to an occurrence of high electrical resistance on the rear defroster circuit, they will also be replaced.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit [GM's website](#).

Recall #: N192217410 | Reduction in Vacuum Brake Assist Canada Only Recall Date: 2019 Jun 27

Recall Description

General Motors has approved a safety recall in Canada for certain 2017 model year Chevrolet Silverado LD, GMC Sierra LD, Cadillac Escalade, Chevrolet Suburban, Chevrolet Tahoe, and GMC Yukon vehicles, that, in some circumstances, may have a condition in which the engine-mounted mechanical vacuum pump output may decrease over time, decreasing the amount of vacuum/power brake assist. If the vacuum level drops, customers may experience increased brake pedal effort, hard brake pedal, and/or potentially increased stopping distance. The Drivers Information Centre (DIC) Service brake assist alert will activate 2-5 minutes after the vacuum level drops, and a Diagnostic Trouble Code (DTC) will also be set. Even where this condition occurs, the hydraulic brake system remains functional. The condition is more prevalent at low speed when softly applying the brakes. Failure to follow recommended oil change intervals could contribute to this condition.

Remedy

Dealers are to reprogram the electronic brake control module (EBCM).

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit [GM's website](#).



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Oct 3		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Feb 3		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Feb 26		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Feb 27		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial
2014 Jul 4	10,073 KM	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Oct 30	22,024 KM	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2014 Dec 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2015 Nov 25		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Dec 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2015 Dec 4		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2015 Dec 14		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 May 16		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Jun 3		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Jul 5		Manitoba, Canada	Non-collision	Front
2016 Jul 5		Insurance Records Manitoba, Canada	Non-collision	Estimate Date: n/a Front
2016 Aug 15		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Aug 24		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Sep 9		CHEVROLET	Recall	Manufacturer Recall Issued Recall # 2016007
2016 Dec 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2017 Jun 29		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N172085440

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Jul 1	Manitoba, Canada	Vandalism	Rear
2017 Jul 1	Insurance Records Manitoba, Canada	Vandalism	Estimate Date: n/a Rear
2017 Dec 1	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2018 Dec 1	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2019 Jun 27	CHEVROLET	Recall	Manufacturer Recall Issued Recall # N192217410
2019 Jun 27	CHEVROLET	Recall	Manufacturer Recall Issued Recall # N192220470
2019 Dec 1	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2020 Dec 1	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2021 Dec 1	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2022 Dec 1	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other titles, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. **Conditions of Use**