



Vehicle History Report #: 43979865
Report Date: January 28, 2023 | 03:52 PM EST
Report Status: Complete
Reference:

2007 CHEVROLET MALIBU LT

Sedan | 4 Cylinders | Gas
1G1ZT58FX7F203580
Country of Assembly: United States
Last Reported Odometer: 134,500 KM



Accident/Damage Records Found



Last Registered In:
Manitoba (Normal)



12 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of January 28, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

1G1ZT58FX7F203580

INCIDENT DATE	DETAILS	AMOUNT
2012 Apr 5	Manitoba, Canada	
	Claim: Collision Front	Not Reported
2022 Dec 15	Winnipeg, Manitoba, Canada	
	Estimate: Front Estimate Date: n/a	Not Reported
	Claim: Non-collision	\$0.00

Registration

This vehicle has been registered in the following locations in Canada (listed oldest to newest):

- In the province of Ontario with Normal branding.
- In the province of Manitoba with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2007 Aug 30		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2007 Sep 8		Vickar Mitsubishi Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
2007 Sep 21		Vickar Mitsubishi Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
2007 Oct 1		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Trim repaired
2007 Oct 25		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Trim repaired
2007 Dec 17		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire repaired
2008 Jul 18		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2009 Aug 26		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Steering/suspension checked Alignment checked Four wheel alignment performed
2010 Jun 17	36,606 KM	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Brake fluid flushed/changed Oil and filter changed Steering/suspension checked Tire repaired Alignment checked One tire replaced

ODOMETER	SOURCE	DETAILS
2017 Jul 31	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Vehicle serviced
2017 Oct 14 124,103 KM	Super Lube Winnipeg, Manitoba, Canada	Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed Oil and filter changed Air filter replaced
2019 Feb 27 134,099 KM	River City Ford Winnipeg, Manitoba, Canada	Vehicle serviced



Open Recalls

Recall #: N130036 | BRAKE LAMP MALFUNCTION Recall Date: 2014 May 14

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in 2004-2012 model year (MY) Chevrolet Malibu, 2004-2007 MY Chevrolet Malibu Maxx, 2005-2010 MY Pontiac G6, 2007-2010 MY Saturn Aura vehicles. On these vehicles, over time an increased resistance can develop in the Body Control Module (BCM) connection system and result in voltage fluctuations or intermittency in the Brake Apply Sensor (BAS) circuit that can cause service brake lamp malfunction. As a result, the service brake lamps may illuminate when the service brakes are not being applied, or may not illuminate when the service brakes are being applied. Additionally, cruise control may not engage. If cruise control is engaged, additional service brake pedal travel may be required to disengage it. Service brake pedal application may not be required to move the shift lever out of PARK, or additional service brake pedal travel may be required to move the shift lever out of PARK. Traction control, electronic stability control, and panic braking assist features, if equipped, may be disabled. Service ESC and/or Traction Control tell-tales may illuminate with this condition.

Remedy

Dealers are to attach the wiring harness to the BCM with a spacer, apply dielectric lubricant to both the BCM and harness connector and on the BAS and harness connector, and relearn the brake pedal home position.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit GM's website.

Recall #: N140152 | TRANSMISSION SHIFT CABLE FRACTURE Recall Date: 2014 Apr 29

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2004-2007 model year Chevrolet Malibu Maxx, 2004-2008 model year Chevrolet Malibu, 2005-2008 model year Pontiac G6, and 2007-2008 model year Saturn AURA vehicles equipped with a 4-speed automatic transmission (ME7/MN5). These vehicles have a condition in which the transmission shift cable may fracture at any time.

Remedy

Dealers are to install a shift cable assembly and mounting bracket.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit GM's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2006 Dec 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2007 Aug 30		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2007 Sep 8		Vickar Mitsubishi Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2007 Sep 21		Vickar Mitsubishi Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2007 Oct 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2007 Oct 1		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2007 Oct 25		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2007 Dec 17		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2008 Feb 28		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2008 Jul 18		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2009 Mar 5		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Aug 26		Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2010 Feb 28		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Jun 17	36,606 KM	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2011 Mar 1		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Feb 28		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Apr 5		Manitoba, Canada	Collision	Front
2013 Feb 28		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed

1G1Z158FX7F203580

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Feb 28	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Apr 29	CHEVROLET	Recall	Manufacturer Recall Issued Recall # N140152
2014 May 14	CHEVROLET	Recall	Manufacturer Recall Issued Recall # N130036
2015 Feb 28	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Feb 28	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Feb 28	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jun 14	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed Dealer took registration of this vehicle while it was in inventory
2017 Jul 6	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2017 Jul 12	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jul 31	Vickar Community Chevrolet Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2017 Oct 14	124,103 KM Super Lube Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Jul 1	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Feb 27	134,099 KM River City Ford Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2019 Mar 5	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2019 Mar 12	134,500 KM Independent Source Winnipeg, Manitoba, Canada	Odometer reading	
2019 Mar 26	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2019 Jul 9	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 20	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jul 9	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed

1G1Z158FX7203580

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Jul 9	Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Dec 15		Non-collision	
2022 Dec 15	Insurance Records Winnipeg, Manitoba, Canada	Unknown	Estimate Date: n/a Front



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, marketable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.



1G1ZT58F7F203580