

UNDERSTANDING YOUR SAFETY

CERTIFICATE OF INSPECTION FOR VEHICLES UNDER 4,500 KG Vehicle Standards and Inspections
1981 Plessis Road, Bldg. B
Box 6300
Winnipeg MB R3C 4A4

Manitoba

Date Inspection Started: DAY MO. YR.
Date Inspection Completed: DAY MO. YR.
Inspection Expiry Date: DAY MO. YR.

TYPE OF VEHICLE: Motorcycle Truck Passenger Car Recreational Vehicle NEW USED

Station Number: Station Name: City: Province: Postal Code: Phone: Mechanic Number: Mechanic Signature: Station Phone Number: Vehicle Owner: Address: Licence Number: V.I.N./Serial Number: Make: Model: Year:

Inspection Result:
 Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Out-of-Service

DRIVER'S CONTROLS				ENGINE COMPARTMENT					
No.	R	C	Item	Ref #	No.	R	C	Item	Ref #
01			Vehicle Identification Number	1-1, M1-1	61			Food and Safety Catch	6-1
02			Neutral Safety Switch	1-6	62			Wiring and Battery	7-1, 2, M7-1,2
03	X		Accelerator Pedal	1-2	63			Vacuum/Hydraulic System	3-6, 8
04			Sun Visors	8-13	64			Brake Master Cylinder	3-2
05			Horn Operation	5-4, M5-2	65			Power Steering	4-8
06			Mirrors	8-11, 12, M5-3	PROPANE/NATURAL GAS				
07			Windshield Wipers & Washers	8-9	66			Structural Members	1-10, 2-10
08			Defroster & Int. Heaters	8-14, 15	67			Pressure Vessel	1-2, 2-2
09	XX		Speedometer, Odometer	3-1, 2, M3-4	69			Damage Protection	1-6, 2-4
10			Windshield and Windows	8-8, 10, M8-4	70			Corrosion Protection	1-6, 2-5
11			Switches	7-3, M7-3	71			Pressure Vessel Filler &	1-6
12			Clutch and Brake Pedal Pad	5-5	72			Main Shut-off Valve	1-4
13			Instrument Panel Lamps	6-3	73			Valves	1-8
14			Parking Brake, Transmission	3-1, 5-3, M1-4	74			Vaporizer	1-9
15			Power Brake Operation	3-7	75			System Piping & Fittings	1-7, 2-7
16			Brake Failure Indicators	3-3	76			Gas Safety Branch Decal	1-1, 2-1
17			Brake Pedal Reserve	3-4, 5, M3-2	77			Relieving Device (Burst Disc)	2-3
18			Clutch Disengagement	1-5	78			Pressure Gauge	2-6
19			Handlebars	M4-1	79			Gasoline Lock-off	2-9
20					80			Pressure Regulator	2-8

RECREATIONAL VEHICLE

No.	R	C	Item	Ref #
80			CSA Z-240 Standard Approval Number	11-1
81			Manitoba Labour Z-240 Standard Approval Number	11-1

F Brake Lining Thickness: Drum/Rotor Measurement: Right
R
O
N Axle 1 Axle 2 Axle 1 Axle 2 Left
T

REMARKS:

I am aware that the above-noted vehicle is unsafe to be operated on a highway due to the noted equipment defects. I undertake to prevent this vehicle from being operated on a highway until the repairs or adjustments have been made to restore it to safe condition and a qualified mechanic has re-inspected the vehicle.

Vehicle Received without repairs by: Signature: Date:

1323-04-B8 MG-3882 (R-08/08) PRESENT THIS COPY WHEN REGISTERING VEHICLE

ITEM HAS FAILED SAFETY INSPECTION AND NEEDS TO BE REPAIRED

ITEMS HAS NOW BEEN REPAIRED, AND HAS NOW PASSED THE SAFETY INSPECTION

CIRCLED # INDICATES ADVISEMENT ONLY

INSPECTION RESULTS

Inspection Result:
 Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Out-of-Service

PASSED SAFETY

Inspection Result:
 Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Out-of-Service

PASSED SAFETY

Inspection Result:
 Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Out-of-Service

FAILED SAFETY

Inspection Result:
 Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Out-of-Service

FAILED SAFETY